

Condensed sample report

Environmental Inspection Report

Client Name: Valued Client

Location Address:

200 Your Street

Anywhere MD 21190

Inspection Date: 11/07/2023

Time of Inspection Time: 2:00 PM

Outside Temperature: 95 F **Outside Humidity%:** 60 RH

Outside Conditions: Partly sunny/cloudy

Indoor Temperature: 75 F **Indoor Humidity%:** 57 RH



Prepared By:

Air Mold Inspection & Testing

Linthicum MD 21090

Condensed sample report

This Report is Meant to be Read in its Entirety

Condensed sample report

Mold Inspection Report

To whom it may concern,

Based upon our findings.....

Elevated Mold Conditions Exist: YES

Professional Mold Remediation Recommended: YES

General Observations/ Notes:

Client had previous water intrusion in the basement which started at the front end of the house..... No visible signs of water or mold damage in the basement Signs of previous water intrusion and suspected mold growth observed underneath kitchen sink on cabinet

Condensed sample report

Mold Inspection Pictures



Figure 1-Mold growth on bathroom ceiling

End of Report